



VDO ist jetzt
Continental.
Original bleibt
Original.

Software Update

TPMS Pro & TPMS Go

Dear Sir or Madam

With this product information we would like to inform you about a new software version, which is now available via the VDO WebTPM application.

New software versions:

- TPMS Pro: DV1-37 (VDO brand), DCE1-37 (Continental brand)
- TPMS Go: HV1-25 (VDO brand), HCE1-25 (Continental brand)

Highlights:

- Brand new models added
- New brand included
- Updated OE sensor information
- Updated relearn information
- Updated aftermarket sensor coverage

Note:

Before updating the device, please make sure that you have the latest WebTPM software (www.continental-aftermarket.com/webtpm, version 8.16). Without the latest version, the update will not be completed. If you need help updating WebTPM, contact our technical support: servicetools@continental-aftermarket.com.

New content for Europe:

Brand new models added:

Audi e-tron/GT/RS; **BMW** M3 (G80); **Borgward** BX7 TS; **Citroën** ë-C4; **DFSK** 500, S560, 580, C32/C35, EC31/EC35, ix7, F5/ix5, S330/S370, and Seres 5/3; **Fiat** Tipo Cross; **Ford** F-150 (14); **Hyundai** Bayon and IONIQ 5; **Lynk & Co** 02, 03, and 05; **McLaren** Artura; **Mercedes-Benz** EQA Class (H243), C Class (206), and EQS Class (297); **Opel** Crossland; **Peugeot** 508 PSE; **Renault** Arkana and Kangoo/Express 3; **Škoda** Fabia 3; **Toyota** Yaris 4 Cross

New brands included:

DFSK

Updated OE sensor / relearn information:

Alpina Automobiles B3 S/B3-D3 BiTurbo and B5/B5 S; **BAIC** BJ40 PLUS; **Dacia** Dokker/Van; **Ford** Focus 4/Turnier; **Hyundai** Elantra (MD/UD); **Mercedes-AMG** GT Class (190); **Mercedes-Benz** B Class (246), GL Class (166), SL Class (230), SLK Class (171); **Mini** Convertible (R57); **Lexus** SC 430; **Lynk & Co** 01; **Mazda** CX-5 (KF), and Mazda6 (GL); **Mini** Clubman (R55), and Coupé; **Nissan** GT-R; **Peugeot** 308/cc/SW/GT/GTi; **Subaru** Forester/e-Boxer; **Toyota** Highlander (XU70), and RAV4 (AX50); **Volvo** S60 2/Cross Country

Updated aftermarket sensor coverage:

α.Sens, Alcar by Schrader, ALCAR Sensor, BH SENS Intellisens BoYu, CYC SENSOR, EU- Pro/T-pro/Hybrid/Hybrid 3.5/NFC, EZ-Sensor, Italsensor 3.0evo, Legends Sensor/MAX SELECT Sensor, MORESENSOR/MAX T.O.T.A.L. Gen1/Gen2, ORANGE, ProSens, Rapid Sensor, Sens.it, UniSens by repstar, WePro sensor, Z-Sensor

A new aftermarket sensor has been added in this version: TYC SENSOR